

November 16, 2022

Regional District of Nanaimo
6300 Hammond Bay Road
Nanaimo, BC V9T 6N2

Attention: **Duncan Taylor**, Manager Engineering Services, Regional & Community Utilities

Subject: **GNPCC No. 3 Grit Tank Inspection Report – For Record**
RDN Ref: Project WW-0038 / Equip: T-113, SRM Ref: P0041

Dear Duncan,

Please find attached my summary report and photographs taken on July 14, 2022, during interior inspection of the GNPCC No. 3 Grit Tank.

This is intended to help inform scope of work decisions made regarding the RDN's GNPCC Grit and Sedimentation Tank Relining project WW-0038. The report photos may be compared to those in the September 2018 Norske tank inspection report, and may be shared with any RDN staff or consultants/contractors involved in planning or execution of the project.

If you have any questions, or require additional information, please don't hesitate to contact me at your convenience.

Sincerely,




Scot Merriam, BASc (mech)
Principal Project Manager

c. Craig Hoover (RDN), Rob Skwarczynski (RDN)

No. 3 Grit Tank Inspection Report – November 16, 2022 Rev 0

Inspection Date:	July 14, 2022
Equipment:	No. 3 Grit Tank, GNPCC
Ref. Number:	T-113
Scope:	Inspect interior of tank, with a focus on the condition of the concrete walls and floor
Method:	Visual, hammer sounding and probe testing. See photo 64 attached for description of tools used. When probe testing, the probe was typically struck four times with the hammer.
Inspection references or samples:	Photographs and annotated drawings attached
Observations:	
<i>Probe Testing</i>	
Location 1 east wall ~ 900 mm up from floor – uncoated concrete	Approximately 12 mm (1/2") penetration; concrete at probe location has turned white, likely a result of process attack. Refer to photos 43 and 44.
Location 2 east wall ~ 1,800 mm up from floor – uncoated concrete	Approximately 12 mm (1/2") penetration; concrete at probe location has turned white, likely a result of process attack. Refer to photos 45 and 46.
Location 3 east wall ~ blister location 1,200 mm up from floor – black (top) and off-white (bottom) coating	Approximately 10 mm (3/8") penetration; concrete at probe location has turned white, likely a result of process attack. Blister in top black coating; off-white coating below seemed reasonably adhered to the concrete. Refer to photos 47 and 48.
Location 4 south wall ~ 600 mm up from floor – Only off-white (bottom) coating remains in this section (black has delaminated and fallen off)	Approximately 10 mm (3/8") penetration; thin surface layer of concrete at probe location has turned white, likely a result of process attack. Concrete below is harder. Blister in top black coating; off-white coating below seemed reasonably adhered to the concrete. Refer to photos 49 and 50.
Location 5 floor ~ 600 mm west of pressure relief valve	Approximately 12 mm (1/2") penetration; concrete at probe location has turned white, likely a result of process attack. Refer to photos 51 and 52.
Location 6 north wall ~ 1,800 mm up from floor – uncoated concrete	Approximately 10 mm (3/8") penetration; concrete at probe location has turned white, likely a result of process attack. Refer to photos 53 and 54.
Location 7 north wall ~ 300 mm up from floor – uncoated concrete	Approximately 12 mm (1/2") penetration; concrete at probe location has turned white, likely a result of process attack. Refer to photos 55 and 56.
Location 8 north wall ~ blister location 2,200 mm up from floor – black coated concrete	Approximately 10 mm (3/8") penetration; concrete at probe location has turned white, likely a result of process attack. Refer to photos 57 and 58.
Location 9 west wall ~ 700 mm up from floor – uncoated concrete	Approximately 12 mm (1/2") penetration; concrete at probe location has turned white, likely a result of process attack. Refer to photos 60 and 61.

<i>Concrete sounding – general</i>	The surface of uncoated concrete was sounded with a hammer in many wall and floor locations while taking photos. In general, the sounding note was muted/dull, suggesting the surface of the concrete has been softened due to process attack (poor quality concrete not suspected due to above probe observations).
<i>Concrete joint scouring</i>	The joint between the north wall and the floor was scoured out from the east wall to the west wall, especially near the mid-section of the wall (refer to photo 59). The northeast corner wall joint was also scoured out from the floor to about half way up the wall (refer to photos 43 and 62).
<i>Previous concrete coating(s)</i>	<p>It appears that a thick, black concrete coating was applied to the upper part of all four walls of the tank. There are many blisters in this coating and one large section on the south wall has delaminated and fallen off. There is visual evidence of an off-white coating, below the black coating, on the east, south and west walls of the tank. This coating appears to have adhered better as no blisters were observed. Refer to photos 12 – 24 and 30 – 32.</p> <p>There is no visual evidence of a coating being applied to the tank floor. Refer to photos 37 – 39.</p>



REVISIONS

ISSUE	DATE	DRN	CH'D	APP'D	DESCRIPTION

DESIGNED: J.WCB

DRAWN: VB

CHECKED: PJB BW 4 July 88

DAYTON & KNIGHT LTD.
CONSULTING ENGINEERS

REGIONAL DISTRICT OF NANAIMO
GREATER NANAIMO W.P.C.C.
CONSTRUCTION OF STAGE II EXPANSION - PHASE II
GRIT TANK No.3 DETAILS


SCALE: 1/4" = 1'-0" OR AS SHOWN

DRAWING No. 22-78-4

SHEET 5 OF 21 ISSUE A

Markup for SRM inspection report issued October 2022

N-INT-212



GENERAL STRUCTURAL NOTES

1. APPLICABLE SPECIFICATIONS AND CODES: CONCRETE CONSTRUCTION SHALL CONFORM TO CSA CAN.3-A23.1-M77 AND CAN.3-A23.2-M77.
2. REINFORCING STEEL DETAILS: ALL DETAILING, FABRICATING AND ERECTION OF STEEL REINFORCING BARS, UNLESS OTHERWISE NOTED, SHALL BE IN ACCORDANCE WITH THE "METRIC SUPPLEMENT" IN CONJUNCTION WITH THE "REINFORCING STEEL MANUAL OF STANDARD PRACTICE" AS AVAILABLE FROM THE WESTERN REINFORCING CONTRACTORS ASSOCIATION.
3. MINIMUM REINFORCEMENT: CONCRETE CONSTRUCTION SHALL BE REINFORCED CONCRETE EXCEPT WHERE PLAIN CONCRETE (P/C) IS SPECIFIED ON THE DRAWINGS, IN WHICH CASE NO REINFORCEMENT SHALL BE USED. CONCRETE THAT IS NOT DESIGNATED P/C AND HAS NO REINFORCEMENT INDICATED SHALL BE REINFORCED ACCORDING TO THE FOLLOWING SCHEDULES:

A1 STEEL FOR WALLS AND SLABS

REINFORCEMENT EACH WAY

<u>THICKNESS</u>	<u>SIZE</u>	<u>SPACING</u>	<u>POSITION</u>
6	10M	12 C/C	ON \bar{t}
8	15M	12 C/C	ON \bar{t}
10	15M	12 C/C	EF
12	15M	12 C/C	EF
14	15M	12 C/C	EF
16	20M	12 C/C	EF
18	20M	12 C/C	EF
20	20M	12 C/C	EF

MASS CONCRETE SHALL BE REINFORCED WITH 15M BARS AT 12" MINIMUM IN ALL FACES.

B) 10M @ 18" SHALL BE USED AS TRANSVERSE TIES IF NO OTHER REINFORCING IS NOTED.

4. CONCRETE COVER: CONCRETE COVER OF REINFORCING BARS, IF NOT SPECIFIED ON THE DRAWINGS, SHALL BE AS FOLLOWS OR SHALL BE EQUAL TO THE DIAMETER OF THE MAIN REINFORCING BAR IT COVERS, WHICHEVER IS LARGER:

	<u>CONDITION</u>	<u>SPECIFIED COVER (inches)</u>
A)	CONCRETE CAST AGAINST GROUND	3
B)	CONCRETE EXPOSED TO EARTH, LIQUIDS OR WEATHER	
	i 20M BARS OR LARGER	2
	ii 10M AND 15M BARS	1 1/2
C)	CONCRETE SLABS OR WALLS NOT EXPOSED TO EARTH, LIQUIDS OR WEATHER	3/4
D)	CONCRETE BEAMS OR COLUMNS	2

NOTE: DETAIL BETWEEN GRIT
SLAB AND WALL AT (H)
SIMILAR EXCEPT
NO WATERSTOP

1" JOINT SEALER

1" JOINT FILLER

6" WATERSTOP

DETAIL A

N. T. S.

CONTROL JOINT BETWEEN GRIT TANK BOTTOM SLAB AND WALLS AT BAYLINE

(14') (12') & (1')

CONSTRUCTION JOINT BETWEEN
GRIT TANK COLLECTOR TROUGH
AND WALLS AT (12) & (1)

WALL SHEAR BOLT

DETAIL $\frac{C}{3}$ $\frac{C}{5}$
N.T.S.


VERTICAL CONSTRUCTION

JOINT FOR WALLS

HORIZONTAL CONSTRUCTION JOINT
FOR WALL ON SLAB
N. T. S.

N-INT-212

[illegible]



Exterior Reference Photos




1. GNPCC No. 3 Grit Tank top, looking northwest.



2. GNPCC grit tanks tops, looking northwest – No. 3 Grit Tank in foreground.

General Interior/Mechanism Reference Photos



3. Collector chain (drive end) and air header, looking east



4. Collector chain and air header, looking west



5. Close-up of collector chain, wear strips and trough looking east.



6. Close-up of collector chain, wear strips and trough looking west.




7. Close-up of drive end idler sprockets at east end of collector trough (portable blue sump pump installed for tank entry only).



8. Close-up of collector trough sump permanent suction piping (white, behind chain).



9. Close-up of tail end sprockets at west end of collector trough.



10. Close-up bottom view of drive end sprockets at east end of tank.




11. Close-up of drive end sprockets at east end of tank, looking north. Black wall coating drip lines/blisters/delaminations visible.




12. South wall of tank at east (drive) end (sump pump hose only installed for tank entry). Note coating (drip lines) on upper wall.



13. Center of south wall of tank. Note blisters in black coating on upper wall (lower concrete is uncoated)



14. South wall of tank near west end. Note blisters in black coating on upper wall (lower concrete is uncoated)



15. South wall of tank at west end. Note blisters in black coating on upper wall (lower concrete is uncoated)



16. East wall of tank and inlet box (at right). Note coating (drip lines) on upper wall.



17. Inlet box looking south. Blistered black coating visible.



18. Inside of inlet box looking at southeast corner



19. Inside of inlet box looking at inlet opening (blanked for entry) and southwest corner



20. Bottom of inlet box.



21. East half of south tank wall. Black coating has blistered and delaminated from off-white coating beneath.



22. West half of south tank wall. Black coating has blistered and delaminated from off-white coating beneath.



23. West wall of tank and wooden outlet baffle.



24. West wall of tank (black coated) and start of wooden outlet baffle.



25. Outlet baffle along west wall.



26. Baffle south end support steel.



27. Baffle south end support steel bottom anchor point.



28. Baffle south end support steel top anchor point.



29. Baffle plank connectors.



30. South end of west tank wall behind baffle.



31. Upper north end of west tank wall behind baffle.



32. Lower north end of west tank wall behind baffle.



33. North end of tank outlet weir (wooden baffle in foreground)



34. South end of tank outlet weir (wooden baffle in foreground)



35. North end of tank outlet weir showing top of tank wall (wooden baffle in foreground)



36. South end of tank outlet weir showing top of tank wall (wooden baffle in foreground)



37. East side of tank bottom (uncoated).



38. Center view of uncoated tank bottom – groundwater pressure relief valve at center (ref. dwg: GN-S-PT-201).



39. West side of tank bottom (uncoated).



40. Tank roof support steel.



41. Tank roof support beam connection at south wall.



42. Tank roof perimeter support at southwest corner.


Specific Interior Reference and Probe Photos



43. East wall probe location 1. Note left corner caulking is scoured out (refer to photo 62 for additional detail).




44. Close-up of probe location 1.



45. East wall probe locations 1 and 2.



46. Close-up of probe location 2



47. East wall probe location 3 near inlet box (beneath blister in black coating).



48. Close-up of probe location 3, beneath blister in black coating. Off-white coating visible beneath black coating.



49. South wall probe location 4, below off-white coating (black top coating has delaminated and fallen off).



50. Close-up of probe location 4.



51. Floor probe location 5, beside pressure relief valve.




52. Close-up of probe location 5.



53. North wall probe location 6.




54. Close-up of probe location 6.



55. North wall probe location 7.



56. Close-up of probe location 7.



57. North wall probe location 8, below blister in black coating.



58. Close-up of probe location 8.



59. Floor to north wall joint caulking scoured out all along.



60. West wall probe location 9 (uncoated concrete).



61. Close-up of probe location 9 (olive and black deposits are not concrete coatings).



62. Northeast wall corner caulking appears to be scoured out.



63. Northwest wall corner not scoured out.



64. Standard household hammer used for concrete sounding and probing, along with wood spike used for probing.