



## **REQUEST FOR TENDER No. 20-030**

### **Pump Station Electrical Kiosks (2) – Remove and Replace**

#### **Addendum 2**

**Issued: May 1, 2020**

**Closing Date & Time: on or before 3:00 PM Pacific Time on May 5, 2020**

#### **Questions & Answers**

- Q1. The kiosk manufacturer is stating they are unable to quote the replacement of the existing fans that was added to the material replacement list on Addendum 2, because there is no information provided in neither the tender package or the Addendum 2 regarding the fan/motor assembly specifications. Is it possible to get those specifications?
- A1. Please see attached photos of the existing fans. The new fans need to have the same specifications and be rated for a Class 1 Div 2 environment.

End of Addendum 3



# LECO<sup>TM</sup> PRODUCTS

V 115 A 1 PH 1  
KW 12 SIZE 12 CY 60  
CFM 1350 CAT. No. A1214E  
SERIAL No. 1749

LONGLEY ELECTRIC Co. Ltd.  
VANCOUVER — B.C.

"INSTALL BEHIND SHUTTERS FOR PROTECTION FROM RAIN."

"CAUTION: MOUNT WITH THE LOWEST MOVING PARTS AT LEAST 8 FEET ABOVE FLOOR OR GRADE LEVEL"

"INSTALLER DERRIERE DES VOILETS POUR PROTEGER DE LA PLUIE."

"ATTENTION: INSTALLER AVEC LES PARTIES MOBILES INFERIEURES AU MOINS A 8 PIEDS AU-DESSUS DU NIVEAU DU PLANCHER OU DU SOL."





EMERSON ELECTRIC CANADA LTD.  
MOTOR DIVISION  
MARKHAM, ONTARIO, CANADA

A.C. MOTOR  
MOTEUR C.A.

MOD

S63KZSRH-6435

H P

1/4

V

RPM

115

CAT

1725

6326C

5.0

HZ

60

SFA

PH

I

SF

1.0

REGIME-RATING

CONT

CL

B

AMB

40

°C

BRUN-BRN

ROUGE-RED

NOIR-BLK

BLEU-BLU

JAUNE-YEL

TO REVERSE ROTATION  
INTERCHANGE RED AND  
BLACK LEADS

400

2

41

MFG NO

D89



LR31351

YOUR CHANGER LEADS OF  
ROTATION INTERCHANGE RED  
CONDUCTORS WITH 115

THERMALLY PROTECTED

REGISTRATION



