

Reattach safety chains to new gangway

Modify existing handrail to widen opening from 1.4m to 1.7m.


Ref. Herold Engineering record drawings in Appendix B for details of existing handrail.

Apply touch-up paint per Note 6 in Structural Steel section of Herold Engineering drawing S01 in Appendix B.

New gangway to include similar transition ramp.

Include 1/2" thick UHMW strip pads bolted to approach deck, as shown, to reduce wear.

1/2" thick UHMW strip pad (typ.)



Replace six (6) damaged planks. Approx. 12' long each.
Lumber to be ACZA treated.



Showing existing area covered by stainless extruded mesh. Fill all uncovered areas with additional mesh for complete coverage on float.



Showing existing area covered by stainless extruded mesh. Fill all uncovered areas with additional mesh for complete coverage on float.

Stainless extruded mesh not required underneath cot ramp.

